

## AMERCOAT 78 HBB CURE

MSDS EU 01 / EN Version 1

Print Date 6/2/2010 Revision date 05-05-09

IDENTIFICATION OF THE SUBSTANCE/PREPARATION AND OF THE COMPANY/UNDERTAKING			
Product information			
Trade name	:	AMERCOAT 78 HBB CURE	
Recommended use	:	coating	
Company	:	PPG Coatings SPRL/BVBA Noordersingel 23 B-2040 Borgerhout	
Telephone	:	+32 3 3606470	
Telefax	:	+32 3 3606435	
Emergency telephone number	:	+31 20 4075210	
E-mail address	:	PMC.Safety@PPG.com	

#### 2. HAZARDS IDENTIFICATION

Symbol(s) : Corrosive

Hazardous components : xylene triethylenetetramine

**R-phrase(s) :** FLAMMABLE. HARMFUL BY INHALATION AND IN CONTACT WITH SKIN. CAUSES BURNS. MAY CAUSE SENSITIZATION BY SKIN CONTACT.

### 3. COMPOSITION/INFORMATION ON INGREDIENTS

Components	EC No.	CAS-No.	DSD	Note	Classification	Concentration
POLYAMINE-EPOXY ADDUCT						>=10.00 - <25.00%
xylene	215-535-7	1330-20-7	25th	Nota C	R10 Xn; R20/21 Xi; R38	>=25.00 - <50.00%
iso-butanol	201-148-0	78-83-1	25th		R67 R10 Xi; R37/38, R41	>=5.00 - <10.00%
ethylbenzene	202-849-4	100-41-4	19th		F; R11 Xn; R20	>=2.50 - <10.00%
			1/8			



# AMERCOAT 78 HBB CURE

MSDS EU 01 / EN Version 1

Print Date 6/2/2010 Revision date 05-05-09

		-		
2,4,6-tris- (dimethylaminomethyl)- phenol	202-013-9	90-72-2	19th	Xn; R22 Xi; R36/38
triethylenetetramine	203-950-6	112-24-3	29th	Xn; R21 C; R34 R43 R52, R53
1-methoxy-2-propanol	203-539-1	107-98-2	19th	R10 >=25.00 - <50.00%
2-methoxypropanol	216-455-5	1589-47-5	25th	R10 Repr.Cat.2; R61 Xi; R37/38, R41

Producer declares that for R-phrases not mentioned in chapters 3, the entire amount of hazardous substances is below limits. For components with an occupational threshold limit value see chapter 8.

If multiple components with identical identifiers appear, these have different hazardous properties, e.g. flashpoint.

### 4. FIRST AID MEASURES

General advice	: When symptoms persist or in all cases of doubt seek medical advice. Never give anything by mouth to an unconscious person.
Eye contact	: Irrigate copiously with clean, fresh water for at least 10 minutes, holding the eyelids apart. Remove contact lenses. Seek medical advice.
Skin contact	: Take off all contaminated clothing immediately. Wash skin thoroughly with soap and water or use recognized skin cleanser. Do NOT use solvents or thinners.
Inhalation	: Remove to fresh air. Keep patient warm and at rest. If breathing is irregular or stopped, administer artificial respiration. If unconscious place in recovery position and seek medical advice.
Ingestion	: If accidently swallowed obtain immediate medical attention. Keep at rest. Do NOT induce vomiting.
Burns	: If spills on clothing catch fire, wash with plenty of water. Remove loose clothing. Do not remove clothing that has melted to the skin.Obtain medical attention.

#### 5. FIRE-FIGHTING MEASURES

Specific hazards during fire fighting	:	As the product contains combustible organic components, fire will produce dense black smoke containing hazardous products of combustion (see section 10). Exposure to decomposition products may be a hazard to health. Cool closed containers exposed to fire with water spray. Do not allow run-off from fire fighting to enter drains or water courses.
Special protective equipment for fire-fighters	:	In the event of fire, wear self-contained breathing apparatus.
Suitable extinguishing media	:	Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Keep containers and surroundings cool with water spray.
Extinguishing media which shall not be used for safety reasons	:	Do NOT use water jet.

### AMERCOAT 78 HBB CURE

MSDS EU 01 / EN Version 1

PPG Protective & Marine Coatings

Print Date 6/2/2010 Revision date 05-05-09

#### 6. ACCIDENTAL RELEASE MEASURES Personal precautions Use personal protective equipment. Ventilate the area. Refer to protective measures listed in sections 7 and 8. Wear respiratory protection. Beware of vapours accumulating to form explosive concentrations. Vapours can accumulate in low areas. Remove all sources of ignition. Try to prevent the material from entering drains or water ways. If the product **Environmental precautions** contaminates rivers and lakes or drains inform respective authorities. Methods for cleaning up Clean with detergents. Avoid solvents. Contain and collect spillage with noncombustible absorbent material, (e.g. sand, earth, diatomaceous earth, vermiculite) and place in container for disposal according to local / national regulations (see section 13). Additional advice Refer to section 15 for specific national regulation. 7. HANDLING AND STORAGE Handling Safe handling advice Avoid exceeding of the given occupational exposure limits (see section 8). Use only in area provided with appropriate exhaust ventilation. Avoid contact with skin, eyes and clothing. Smoking, eating and drinking should be prohibited in the application area. Avoid inhalation of vapour or mist. For personal protection see section 8. Advice on protection against Prevent the creation of flammable or explosive concentrations of vapour in air and avoid vapour concentration higher than the occupational exposure fire and explosion limits. When transferring from one container to another apply earthing measures and use conductive hose material. No sparking tools should be used. Operators should wear anti-static footwear and clothing and floors should be of the conducting type. Isolate from sources of heat, sparks and open flame. Take necessary action to avoid static electricity discharge (which might cause ignition of organic vapours). The product should only be used in areas from which all naked lights and other sources of ignition have been excluded. No smoking. The accumulation of contaminated rags and dry overspray, particularly in spray booth filters, may result in spontaneous combustion. Good housekeeping standards, regular safe removal of waste materials and regular maintenance of spray booth filters will minimise the risks of spontaneous combustion and other fire hazards. Storage **Requirements for storage areas** Observe label precautions. Prevent unauthorized access. Containers which and containers are opened must be carefully resealed and kept upright to prevent leakage. Store between 5 and 30°C (41 - 86 F) in a dry, well ventilated place away from sources of heat, ignition and direct sunlight. Solvent vapours are heavier than air and may spread along floors. Vapours may form explosive mixtures with air. Electrical installations / working materials must comply with the technological safety standards. Keep away from sources of ignition - No smoking. Store in accordance with the particular national regulations (see section 15). Keep away from oxidising agents and strongly acid or alkaline materials. Advice on common storage 8. EXPOSURE CONTROLS/PERSONAL PROTECTION

Components		CAS-No.	Value [mg/m <sup>3</sup> ]	Value [ppm]	Basis		
Personal protective equipment						-	
General advice							
		3/	8				

# AMERCOAT 78 HBB CURE

MSDS EU 01 / EN Version 1

PPG Protective & Marine Coatings

Print Date 6/2/2010 Revision date 05-05-09

Respiratory protection	: When operators, whether spraying or not, have to work inside the spray booth, ventilation is unlikly to be sufficient to control particulates and solve vapour in all cases. In such circumstances they should wear a compressed a fed respirator during the spraying process and until such time as the particulates and solvent vapour concentration has fallen below the exposure limits.
Hand protection	<ul> <li>For prolonged or repeated contact use protective gloves.</li> <li>For prolonged or repeated contact use protective gloves.</li> <li>Barrier creams may help to protect the exposed areas of skin, they should however not be applied once exposure has occurred.</li> <li>Skin should be washed after contact.</li> <li>Use chemical resistant gloves classified under Standard EN 374: Protective gloves against chemicals and micro-organisms.</li> </ul>
	Recommended gloves: Product is corrosive. Please contact your hand protection supplier for further advice.
	When prolonged or frequently repeated contact may occur, a glove with a protection class of 6 (breakthrough time greater than 480 minutes according to EN 374) is recommended. When only brief contact is expected, a glove with a protection class of 2 or higher (breakthrough time greater than 30 minutes according to EN 374) is recommended. NOTICE: The selection of a specific glove for a particular application and duration of use in a workplace should also take into account all relevant workplace factors such as, but not limited to: Other chemicals which may b handled, physicalrequirements (cut/puncture protection, dexterity, thermal protection), potential body reactions toglovematerials, as wellas the instructions/specifications provided by the glove supplier.
Eye protection Skin and body protection	<ul> <li>Chemical resistant goggles must be worn.</li> <li>Personnel should wear protective clothing. Skin should be washed after contact.</li> </ul>
Additional advice	contact.
Environmental protection	: Refer to national regulations in chapter 15 for regulations on environmenta protection.
Personal protection Protective equipment	: P3A3 full-face combi mask, safety gloves, safety suit and boots
Please contact your personal pr	otection equipment supplier for further advice
HYSICAL AND CHEMICAL P	ROPERTIES
Form	: viscous
Colour Odour	: mild aromatic
Flash point	: 25.0 °C
	Note: Calculated
Autoignition temperature	: Note: no data available
	4/8

# AMERCOAT 78 HBB CURE

MSDS EU 01 / EN Version 1

PPG PPG Protective & Marine Coatings

Print Date *6/2/2010* Revision date *05-05-09* 

is g/m3 (V) g/m3 /cm3 C cally insoluble a available at <23 °C versal section: 6 mm d: ISO 2431 (EN 535) 6 mm CUP temperatures above 60°C (140 F), direct sunlight and contact with s of heat. way from oxidising agents, strongly alkaline and strongly acid als in order to avoid exothermic reactions. of fire hazardous decomposition products may be produced such as: n dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx), black smoke.
g/m3 /cm3 C cally insoluble a available at <23 °C versal section: 6 mm d: ISO 2431 (EN 535) 6 mm CUP temperatures above 60°C (140 F), direct sunlight and contact with s of heat. way from oxidising agents, strongly alkaline and strongly acid als in order to avoid exothermic reactions. e of fire hazardous decomposition products may be produced such as: n dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx),
C cally insoluble a available at <23 °C versal section: 6 mm d: ISO 2431 (EN 535) 6 mm CUP temperatures above 60°C (140 F), direct sunlight and contact with s of heat. way from oxidising agents, strongly alkaline and strongly acid als in order to avoid exothermic reactions. e of fire hazardous decomposition products may be produced such as: n dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx),
cally insoluble a available at <23 °C versal section: 6 mm d: ISO 2431 (EN 535) 6 mm CUP temperatures above 60°C (140 F), direct sunlight and contact with s of heat. way from oxidising agents, strongly alkaline and strongly acid als in order to avoid exothermic reactions. e of fire hazardous decomposition products may be produced such as: n dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx),
at <23 °C versal section: 6 mm d: ISO 2431 (EN 535) 6 mm CUP temperatures above 60°C (140 F), direct sunlight and contact with s of heat. way from oxidising agents, strongly alkaline and strongly acid als in order to avoid exothermic reactions. e of fire hazardous decomposition products may be produced such as: n dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx),
temperatures above 60°C (140 F), direct sunlight and contact with s of heat. way from oxidising agents, strongly alkaline and strongly acid als in order to avoid exothermic reactions. e of fire hazardous decomposition products may be produced such as: n dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx),
s of heat. away from oxidising agents, strongly alkaline and strongly acid als in order to avoid exothermic reactions. e of fire hazardous decomposition products may be produced such as: n dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx),
s of heat. away from oxidising agents, strongly alkaline and strongly acid als in order to avoid exothermic reactions. e of fire hazardous decomposition products may be produced such as: n dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx),
als in order to avoid exothermic reactions. e of fire hazardous decomposition products may be produced such as: n dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx),
n dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx),
is no data available for this product. eparation has been assessed following the conventional method of the rous Preparations Directive 1999/45/EC and classified for
logical hazards accordingly. See Sections 3 and 15 for details. ted or prolonged contact with the preparation may cause removal of
l fat from the skin resulting in desiccation of the skin. ause irreversible eye damage. is no data available for this product.
2-2)
LD50: 1,200 mg/kg (rat)
LD50: 805 mg/kg (rabbit )
eparation has been assessed following the conventional method of the
rous Preparations Directive 1999/45/EC and is not classified as rous for the environment. See section 3 for details on components.
0

## AMERCOAT 78 HBB CURE

MSDS EU 01 / EN Version 1

PPG Protective & Marine Coatings

Print Date 6/2/2010 Revision date 05-05-09

## 13. DISPOSAL CONSIDERATIONS

Product	:	The product should not be allowed to enter drains, water courses or the soil. Disposal together with normal waste is not allowed. Special disposal required according to local regulations.
Waste key for the unused product	:	The European Waste Catalogue classification of this product, when disposed of as waste is:
		08 01 12 Waste paint and varnish other than those mentioned in 08 01 11.
		If this product is fully cured or mixed with other wastes, this code may no longer apply. If mixed with other wastes, the appropriate code should be assigned. For further information contact your local waste authority

### 14. TRANSPORT INFORMATION

Transport within user's premises: always transport in closed containers that are upright, labelled and secure. Ensure that persons transporting the product know what to do in the event of an accident or spillage.

Transport to be in accordance with ADR for road, IMDG for sea and IATA for air transport:

UN-Number	:	3469
Proper shipping name	:	PAINT RELATED MATERIAL, FLAMMABLE, CORROSIVE
Class	:	3
Sub Class	:	8
Packing group	:	III
Label	:	3 + 8
Proper shipping name (ADR)	:	PAINT RELATED MATERIAL, FLAMMABLE, CORROSIVE
Marine Pollutant (IMDG)		: -
EmS (IMDG)		: F-E, S-C
Limited quantity (ADR)		: Max. per inner pack. : 5.00 L
		Max. per outer pack. : 30.00 KG
Limited quantity (IMDG)		: Max. per inner pack. : 5.00 L
		Max. per outer pack. : 30.00 KG

#### **15. REGULATORY INFORMATION**

The product is classified and labelled in accordance with Directive 1999/45/EC.



Hazardous components which must be listed on the label:

- xylene
- triethylenetetramine

# AMERCOAT 78 HBB CURE

MSDS EU 01 / EN Version 1



Print Date *6/2/2010* Revision date *05-05-09* 

R-phrase(s)	: R10 R20/21 R34 R43	Flammable. Harmful by inhalation and in contact with skin. Causes burns. May cause sensitization by skin contact.
S-phrase(s)	: S23	Do not breathe spray.
	S26	In case of contact with eyes, rinse immediately with plenty of water and seek medical advice.
	S36/37/39	Wear suitable protective clothing, gloves and eye/face protection.
	S38	In case of insufficient ventilation, wear suitable respiratory equipment.
	S45	In case of accident or if you feel unwell, seek medical advice immediately (show the label where possible).

The information contained in this safety data sheet does not constitute the user's own assessment of workplace risks, as required by other health and safety legislation. The provisions of the national health and safety at work regulations apply to the use of this product at work.

#### National legislation

#### **16. OTHER INFORMATION**

### Explanation of R-phrases mentioned in section 3

xylene	R10 R20/21 R38	Flammable. Harmful by inhalation and in contact with skin. Irritating to skin.
iso-butanol	R10 R37/38 R41 R67	Flammable. Irritating to respiratory system and skin. Risk of serious damage to eyes. Vapours may cause drowsiness and dizziness.
ethylbenzene	R11 R20	Highly flammable. Harmful by inhalation.
2,4,6-tris-(dimethylaminomethyl)-phenol	R22 R36/38	Harmful if swallowed. Irritating to eyes and skin.
triethylenetetramine	R21 R34 R43 R52/53	Harmful in contact with skin. Causes burns. May cause sensitization by skin contact. Harmful to aquatic organisms, may cause long-term adverse effects in the aquatic environment.
1-methoxy-2-propanol	R10	Flammable.

7/8

# AMERCOAT 78 HBB CURE

MSDS EU 01 / EN Version 1

PPG Protective & Marine Coatings

Print Date 6/2/2010 Revision date 05-05-09

2-methoxypropanol	R61	May cause harm to the unborn child.
	R10	Flammable.
	R37/38	Irritating to respiratory system and skin.
	R41	Risk of serious damage to eyes.

This Safety Data Sheet is based on the Safety Data Sheets obtained from the producer/manufacturer or/and internet databases and valid regulations considering hazardous substances/preparations.

Training advice:

Persons taking part in a turnover of hazardous products ought to be trained in product handling, safety and hygiene.

Drivers ought to be trained and obtain a certificate in accordance with the requirements of transport regulations (ADR).

Version: 1

#### Revision date 05.05.2009

The information contained in this safety data sheet is based on the present state of knowledge and current European and National legislation at the date of issue. The supplier reserves the right to modify data on the safety data sheet without further notice. Any change in data will normally be followed by the issue of a new safety data sheet. The user should check the date of issue and if more than 12 months have elapsed, then the data should only be used after checking with the nearest sales office of the supplier to establish that the data is still valid. As the specific conditions of use of the product are outside the suppliers control, the supplier is not reponsible for the (negative) consequences of these specific conditions of use, which are outside of the suppliers control and which are not compliant with the handling, storage and other instructions in this safety data sheet.

After all component(s) stated on the relevant Technical Data Sheet have been mixed the safety precautions mentioned on each of the component(s) safety data sheets and labels should be used in assessing the safety precautions of the mixed product.